CERTIFICATE OF COMPLIANCE

Certificate Number EX28188

Report Reference EX28188-2019-09-17

Date 2021-March-22

Issued to: DUYAR VANA MAKINA SAN VE TIC A S

Osmangazi Mh. 2653 Sk. No:7 EsenyurtIstanbul 34522 TR

This is to certify that representative samples of

BUTTERFLY VALVES

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1091, Butterfly Valves for Fire-Protection Service.

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

(II)

CERTIFICATE OF COMPLIANCE

Certificate Number EX28188

Report Reference EX28188-2019-09-17

Date 2021-March-22

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Product Designation(s):

Model	Nominal Pipe Size, NPS	Rated Pressure, psig	End Configuration	Indicator Post	Supervisory Switch*
Y-4020	2-1/2, 3, 4, 5, 6 and 8	300	Wafer		1/0
Y-4025	2-1/2, 3, 4, 5, 6 and 8	300	Grooved		1/0

^{*}I = Indoor installation; O = Outdoor installation

Bambles

Bruce Mahrenholz, Director North American Certification Program

(U)

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/